

DATE: November 11, 2003

SUBJECT: RX8 HVAC Temp & Fan Dial Availability

REFERENCE NO: RF- 03-28

It is no longer necessary to replace the heater control unit (FE01-61-190) in order to obtain the temperature and / or fan control dials due to breakage. Part numbers have been established for each part. Technical Service Bulletin # 07-003/03 addressing this issue has also been released (11/3/2003) to service personnel.

**IMPORTANT!** Although only one dial may be damaged, both temperature & fan dials should be replaced as a pair.

Replacement of Temperature and / or Fan Dials		
Old Part Number	New Part Number	Description
FE01-61-190	N/A	Heater control unit
N/A	FE62-61-195	Temperature control dial
N/A	FE61-61-195	Fan control dial

