

## 2006 Mazda RX-8 2RTR, 1.3L (1308 cc)

JM1FE173660205445

Odometer: 92,821 miles

### 3 Confirmed Codes

- P0171** System Too Lean Bank 1
- P0138** O2 Sensor Circuit High Voltage Bank 1 Sensor 2
- P0455** EVAP System Leak Detected (large leak)

### 2 Pending Codes

- P0171** System Too Lean Bank 1
- P0455** EVAP System Leak Detected (large leak)

### 0 Permanent Codes

### 7 Powertrain Control Module Codes

- P0571** Brake Switch "A" Circuit
- P0138** O2 Sensor Circuit High Voltage Bank 1 Sensor 2
- P0171** System Too Lean Bank 1
- P0410** AIR System
- P0455** EVAP System Leak Detected (large leak)
- P0411** AIR System Incorrect Flow Detected

**P0037** HO2S Heater Control Circuit Low Bank 1 Sensor 2

### 1 Remote Keyless Entry Code

**B1131** No description available

### 1 Anti-Lock Brake Module Code

**B1484** No description available

### 3 Restraint control Module Codes

**B1998** No description available

**B1994** No description available

**B2290** No description available

**Disclaimer:** This information is provided without warranty and is subject to the Terms of Use posted at [www.bluedriver.com/eula.html](http://www.bluedriver.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.